


2026 Toyota Sequoia SR5 4 Door Utility 3.5L 6 Cyl Hybrid Injected Turbocharged Base 4WD

Exterior Color	License	VIN	Drivable
040 ([redacted])	WY-22P644X	7SVAAABA3TX086032	Unknown

Odometer	Mitchell Service Code
16417	912657

Unit ID
0557678

Options

4 Wheel Drive	4WD or AWD	Air Conditioning	Alum/Alloy Wheels	AM-FM Stereo
Anti-Lock Brake Sys. (ABS)	Auto Air Condition	Automatic Headlights	Auxiliary Input	Bluetooth Wireless Connectivity
Cloth Seat	Cruise Control	Daytime Running Lights	Driver Seat With Power Lumbar Support	Driver-Front Air Bag
Dual A/C	Electric Defogger	Electronic Parking Aid	Electronic Stability Control	First Row Bucket Seat
Fog Lights	Front Heated Seats	Front Seats With Power Lumbar Support	HD Radio	Heated Mirror
Interior Automatic Day/Night Or Electrochromatic Mirror	Keyless Entry System	Leather Steering Wheel	Left-Curtain Air Bag	Manual Sunroof
MP3 Player	Passenger-Front Air Bag	Power Door Locks	Power Driver Seat	Power Folding Exterior Mirrors
Power Passenger Seat	Power Remote Mirror	Power Steering	Power Windows	Rear Bench Seat
Rear Gate Wiper	Rear Heating, Ventilation & Air Conditioning	Rear Spoiler	Rearview Camera	Remote Vehicle Starter System
Running Boards	Satellite Radio	Second Row Side Airbag With Head Protection	Side Airbags	Side Blind Zone Alert
Skid Plate	Smart Key System	Steering Wheel Mounted Audio Control	Telematic Systems	Theft Deterrent Sys.
Third Row Seat	Tilt Steering Wheel	Tire Pressure Monitoring System	Traction Control/Electronic	Trailer Hitch
Trip Computer	Universal Garage Door Opener			

Mitchell Cloud Estimating™
Copyright 1994-2026 Mitchell International, Inc.
All Rights Reserved

Hertz Rent A Car | 2026 Toyota Sequoia SR5

Parts Profile
N/A

Parts Profile Version
N/A

			LABOR			PART				
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Front Bumper										
1	AUTO	Frt Bumper Cover Assy	Overhaul	Body	4.6#	Existing				
2	200072	Frt Bumper Cover	Remove / Replace	Body	INC#	New	52119-0C950	1	[redacted]	
3	AUTO	Frt Bumper Cover	Refinish Only	Refinish	2.8 C					
4	200074	L Frt Bumper Cover Support	Remove / Replace	Body	INC#	New	52116-0C140	1	[redacted]	
5	200166	Frt Bumper Valance Panel	Remove / Replace	Body	INC#	New	53911-0C170	1	[redacted]	
6	200171	Frt Lwr Bumper Spoiler	Remove / Replace	Body	INC#	New	53851-0C120	1	[redacted]	
7	200112	L Frt Otr Parking Sensor Unit	Remove / Replace	Body	0.1#	New	89341-K0060-A0	1	[redacted]	
8	AUTO	Frt Bumper Cover	Remove / Install	Body	INC#					
9	203384	Frt Bumper Wiring Harness	Remove / Replace	Body	INC	New	82114-AN270	1	[redacted]	
Grille										
10	202671	Grille	Remove / Replace	Body	0.9#	New	53114-0C280	1	[redacted]	
11	AUTO	Add W/Front View Camera	Remove / Replace	Body	0.2#					
Front Lamps										
12	202920	L Frt Combination Lamp Assembly	Remove / Replace	Body	0.4#	New	81160-0C230	1	[redacted]	
13	AUTO	Headlamps	Check / Adjust	Body	0.4					
Cooling										
14	202839	L Cooling Intercooler -M	Remove / Replace	Mechanical	1.6#	New	16550-70050	1	[redacted]	
15	202840	R Cooling Rad Mtg Bracket	Remove / Replace	Body	0.3#	New	16582-F4010	1	[redacted]	
Front Fender										
16	202884	L Fender Panel	Remove / Replace	Body	2.2#	New	53812-0C100	1	[redacted]	
17	AUTO	L Front Combination Lamp	Remove / Install	Body	INC#					
18	AUTO	L Fender Outside	Refinish Only	Refinish	2.1 C					
19	AUTO	L Add To Edge Fender	Refinish Only	Refinish	0.5 C					
20	202951	L Fender Front Liner	Remove / Replace	Body	INC#	New	53876-0C100	1	[redacted]	
21	202754	L Fender Adhesive Wheel Opening Mldg	Remove / Replace	Body	0.3	New	75086-0C903	1	[redacted]	
Wheel										
22	200788	Alloy Wheel	Remove / Replace	Body	0.3	New	[42611-0C280]	1	[redacted]	
Windshield										

Mitchell Cloud Estimating™
Copyright 1994-2026 Mitchell International, Inc.
All Rights Reserved

			LABOR			PART				
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
23	200532	W/Shield Glass	Remove / Replace	Glass	3.3#	New	56101-0C210	1	[redacted]	
Cowl & Dash										
24	201824	Cowl Top Grille	Remove / Install	Body	INC#	Existing				
Instrument Panel										
25	200610	Instrument Panel Assy -M	Remove / Install	Mechanical	5.0#	Existing				
Center Console										
26	200611	Ctr Console	Remove / Install	Body	INC	Existing				
Rocker / Pillars / Floor										
27	202617	L Cowl/Dash Hinge Pillar	Remove / Replace	Body	15.2#	New	61114-0C020	1	[redacted]	
28	AUTO	L Hinge Pillar	Refinish Only	Refinish	1.6 C					
Front Seat										
29	203084	Driver Side Seat Adjuster	Remove / Install	Body	0.5*	Existing				
Front Door										
30	201349	L Frt Door Shell (Alum)	Remove / Replace	Body	6.5#	New	67002-0C140	1	[redacted]	
31	AUTO	L Frt Door Outside	Refinish Only	Refinish	2.1 C					
32	AUTO	L Frt Add For Jambs & Interior	Refinish Only	Refinish	1.0 C					
33	AUTO	L Frt Add To R&I/R&R Side Air Bag Sensor	Remove / Replace	Mechanical	0.3					
34	203088	L Frt Door Front Blackout Tape	Remove / Replace	Body	0.3#	New	75926-AN010	1	[redacted]	
35	203090	L Frt Door Rear Blackout Tape	Remove / Replace	Body	0.3#	New	75922-AN010	1	[redacted]	
36	201410	L Frt Otr Door Belt Moulding	Remove / Replace	Body	INC#	New	75720-0C040	1	[redacted]	
37	900501	Per Toyota Non-Reusable Part								
38	AUTO	L Frt Rear View Mirror	Remove / Install	Body	INC#					
39	201473	L Frt Door Cover	Remove / Replace	Body	INC#	New	67832-0C050	1	[redacted]	
40	AUTO	L Frt Door Trim Panel	Remove / Install	Body	INC					
41	201500	L Frt Door Latch Assembly	Remove / Install	Body	INCr#	Existing				
42	201548	L Frt Upr Door Hinge	Remove / Replace	Body	0.3#	New	68720-0C020	1	[redacted]	
43	AUTO	L Frt Door Assembly	Remove / Install	Body	INC					
44	AUTO	L Frt Upr Hinge	Refinish Only	Refinish	0.5 C					
45	201550	L Frt Lwr Door Hinge	Remove / Replace	Body	0.3#	New	68740-0C010	1	[redacted]	
46	AUTO	L Frt Lwr Hinge	Refinish Only	Refinish	0.5 C					
47	201552	L Frt Door Weatherstrip	Remove / Replace	Body	INC	New	67862-0C050	1	[redacted]	

Mitchell Cloud Estimating™
Copyright 1994-2026 Mitchell International, Inc.
All Rights Reserved

			LABOR			PART				
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Rear Door										
48	200469	L Rear Door Shell (HSS)	Remove / Replace	Body	6.8	New	67004-0C190	1	[redacted]	
49	AUTO	L Rear Door Outside	Refinish Only	Refinish	2.1 C					
50	AUTO	L Rear Add For Jambs & Interior	Refinish Only	Refinish	1.0 C					
51	AUTO	L Rear Add To R&I/R&R Side Air Bag Senso	Remove / Replace	Mechanical	0.3					
52	200763	L Rear Door Moulding	Remove / Replace	Body	INC	New	75062-0C010	1	[redacted]	
Quarter Panel										
53	202015	L Quarter Outer Panel	Repair	Body	5.0*#	Existing				
54	AUTO	L Quarter Panel Outside	Refinish Only	Refinish	2.1 C	Existing				
55	201319	L Frt Quarter Wheel Opening Mldg	Remove / Install	Body	0.2	Existing				
56	201322	L Rear Quarter Wheel Opening Mldg	Remove / Install	Body	INC	Existing				
57	201761	L Rear Quarter Wheel Opening Mldg	Remove / Replace	Body	0.3	New	75606-0C030	1	[redacted]	
Rear Lamps										
58	202702	L Rear Combination Lamp	Remove / Install	Body	0.3#	Existing				
Rear Bumper										
59	202988	Rear Bumper Cover	Remove / Install	Body	1.4#	Existing				
60	AUTO	R Rear Quarter Wheel Opening Mldg	Remove / Install	Body	0.3					
61	200341	Rear Bumper Cover	Repair	Body	3.5*#	Existing				
62	AUTO	Rear Bumper Cover	Refinish Only	Refinish	2.8 C	Existing				
Additional Costs & Materials										
63	AUTO	Paint/Materials	Additional Cost						[redacted]	
Additional Operations										
64	AUTO	Clear Coat	Additional Operation	Refinish	4.4				[redacted]	
65	933006	Frame/Rack Set Up	Additional Operation	Frame	2.5*				[redacted]	
66	933031	Pull For Mash	Additional Operation	Frame	4.0*				[redacted]	
Special / Manual Entry										
67	900500	LT Cowl kick panel	Remove / Install	Body*	0.2*	Existing				
68	900500	LT R&I running board	Remove / Install	Body*	0.5*	Existing				
69	900500	Calibrate front radar sensor	Additional Cost						[redacted]	

***** Judgment Item
C Included in Clear Coat Calculation
T Included in Two Tone Calculation
A Included in Clear Coat and Two Tone Calculation
Labor Note Applies
r CEG R&R Time Used for this Labor Operation
d Discontinued by Manufacturer
[ ] Verify the part number and price before ordering

Mitchell Cloud Estimating™
Copyright 1994-2026 Mitchell International, Inc.
All Rights Reserved

Estimate Totals

Labor	Units	Rate	Sublet	Add'l Amount	Totals
Body Labor	51.6	[redacted]			[redacted]
Refinish Labor	23.5	[redacted]			[redacted]
Glass Labor	3.3	[redacted]			[redacted]
Frame Labor	6.5	[redacted]			[redacted]
Mechanical Labor	7.2	[redacted]			[redacted]
Total Labor	**92.1**				[redacted]

Taxable	[redacted]
Tax [redacted]00%	[redacted]
Non-Taxable	[redacted]
Pre-Tax Discount [redacted]%	[redacted]
Labor Total	[redacted]

Parts	Amount
Taxable Parts	[redacted]

Parts Adjustments	[redacted]
Tax [redacted]00%	[redacted]
Non-Taxable	[redacted]
Pre-Tax Discount [redacted]%	[redacted]
Parts Total	[redacted]

Costs	Amount	
Paint Materials	[redacted]	[redacted]
Shop Materials	[redacted]	[redacted]
Other Additional Costs	[redacted]	[redacted]

Paint Materials:
- Refinish Units: 23.5 units
- Rate: [redacted]
- Rate Max: 99.9 units
- Additional Rate: [redacted]

Taxable	[redacted]
Tax [redacted]00%	[redacted]
Non-Taxable	[redacted]
Pre-Tax Discount [redacted]%	[redacted]
Costs Total	[redacted]

Gross Totals	Amount	
Gross Total	[redacted]	[redacted]

Taxable	[redacted]
Tax	[redacted]
Non-Taxable	[redacted]
Pre-Tax Discount [redacted]%	[redacted]
Gross Total	[redacted]

Adjustments	Amount	
Total Customer Responsibility		[redacted]

Net Estimate Total [redacted]

Estimate Event Log

Job Created	10/31/2026 10:48 AM
Estimate Started	10/31/2026 10:53 AM
Estimate Printed	10/31/2026 11:11 AM
Estimate Committed	Estimate Not Committed
Estimate Retrieval ID	1013206661

Mitchell Cloud Estimating™
Copyright 1994-2026 Mitchell International, Inc.
All Rights Reserved