

*** PRELIMINARY ESTIMATE ***

08/06/2026 08:37 AM

Owner

Control Information

Claim # : 15652335

Insured Policy # :

Inspection

Inspection Date: 08/06/2026 08:38 AM

Inspection Type:

Repairer

Target Complete Date/Time:

Days To Repair: 7

Vehicle

2025 Mitsubishi Outlander Sport S 4 DR Wagon
4cyl Gasoline 2.0
Continuously Variable Tr

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: JA4ARUAU5SU008667
Mileage Type: Actual
Code: G7653C
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)	2nd Row Head Airbags	4-Wheel Drive
AM/FM Radio	Air Conditioning	All-Terrain Tires
Armrest(s)	Automatic Dimming Mirror	Automatic High Beam
Automatic Power Locks	Cargo Lamp	Carpeting
Chrome Grille	Collision Avoidance Sys	Color-Keyed Bumper(s)
Compact Spare Tire	Digital Clock	Driver Information Sys
Driver Knee Airbag	Dual Airbags	Elect. Stability Control
Electric Steering	Fwd. Collision Alert	Head Airbags
Interior Lighting	Intermittent Wipers	Keyless Entry System
LED Brakelights	LED Daytime Running Lts	LED Headlamps
Lane Departure Alert	Lighted Entry System	Perimeter Alarm System
Power Door Locks	Power Windows	Privacy Glass


Pwr Accessory Outlet(s)	Rain-Sensing W/S Wipers	Rear Center Arm Rest
Rear Lip Spoiler	Rear View Camera	Rear Window Defroster
Rear Window Wiper/Washer	Side Airbags	Single Exhaust System
Spring Suspension	Steel Wheels	Strg Wheel Radio Control
Temperature Gauge(s)	Theft Deterrent System	Tilt & Telescopic Steer
Tire Pressure Monitor	Trip Computer	USB Audio Input(s)
Velour/Cloth Seats	Wireless Phone Connect	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.		ADJ%	B%	Hours	R
<u>Stripes And Mouldings</u>										
1	E	1517		Mldg,Wheel Opening LT	5220BA33				INC	SM
<u>Front Bumper</u>										
2	E	14		Cover,Front Bumper	62022WE10P				3.2	SM
3	L	14	13	Cover,Front Bumper	Refinish				3.8	RF
					2.7 Surface					
					0.6 Two-stage setup					
					0.5 Two-stage					
4	E	32		Duct,Air Intake	6400J845				INC	SM
5	E	506		Filler,Front Bumper LT	62473W001P				INC	SM
6	E	1061		Filler,Front Bumper LT	6407A367				INC	SM
7	E	1124		Filler,Front Bumper LT	62081W000P				INC	SM
<u>Front End Panel And Lamps</u>										
8	E	33		Grille Assembly	7450B399				INC	SM
9	E	41		Headlamp Assy,Led LT	8301D571				INC	SM
10	N	973		Headlamps Aim	Additional Labor				0.4	SM
11	E	47		Bracket,Indicator Lamp LT	8315A089				INC	SM
12	E	43		Lamp,Side Marker LT	8315A085				INC	SM
<u>Cooling And Air Conditioning</u>										
13	E	815		Cooler,Trans Oil	2920A103				2.2	ME
14	E	1489		Brkt,Trans Oil Cooler	2920A244				INC	ME
<u>Front Body And Windshield</u>										
15	E	103		Fender,Front LT	63113W060P				1.8	SM
16	L	103		Fender,Front LT	Refinish				3.5	RF
					2.4 Surface					
					0.5 Edge					
					0.6 Two-stage					
17	E	498		Brkt,Front Fender LT	5220G408				0.1	SM
<u>Front Body Interior Sheetmetal</u>										
18	E	333		Gusset,Inner Fender LT	5220F299				0.4	SM
19	L	333		Gusset,Inner Fender LT	Refinish				0.5	RF
					0.4 Surface					
					0.1 Two-stage					
20	E	118		Skirt,Inner Fender LT	63841W030P				0.1	SM
21	E	81		Brkt,Front Fender LT	5220AQ07				1.0	SM
22	L	81		Brkt,Front Fender LT	Refinish				0.2	RF
					0.2 Surface					
<u>Front Doors</u>										
23	BR	207		Door Shell,Front LT	Blend Refinish				1.3	RF
					0.9 Blend					
					0.4 Two-stage					


24	RI	231	Pnl,Inner Door Trim LT	R & I Assembly	INC	SM
25	RI	243	Mldg,Front Door Belt LT	R & I Assembly	0.2	SM
26	RI	229	Housing,Mirror Outer LT	R & I Assembly	0.7	SM
27	RI	485	Handle,Front Door Otr LT	R & I Assembly	0.4	SM

Manual Entries

28	L	M14	Corrosion Protection	Refinish		0.3*	RF*
29	L	M15	Color Tint	Refinish		0.8*	RF*
30	L	M17	Cover Car Exterior	Refinish		0.2*	RF*
31	SB	M60	Hazardous Waste Removal	Sublet Repair			SM*
32	N		Pre-scan	Additional Labor		1.0*	ME*
33	N		Post-scan	Additional Labor		1.0*	ME*
33 Items							

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts	
Other Parts	
Paint & Materials	
Parts & Material Total	

Labor	Rate	Replace	Repair Hrs	Total Hrs
			Hrs	

				
--	--	--	--	--

ClaimID: 37507527-AAB1-41DF-AB36-7E903526CA35
Alternate Parts No
SPPL Yes Zip Code: 00000 Default
Rate Name Default

Audatex Estimating 10.38.82 ES 08/06/2026 09:49 AM REL 10.38.82 DT 07/01/2026 DB 08/01/2026
State Disclosure:MN
© 2026 Audatex North America, LLC.

A 50% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate.
2.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS
SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE.
WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE PARTS

MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.
A PERSON WHO FILES A CLAIM WITH INTENT TO DEFRAUD OR HELPS COMMIT A FRAUD
AGAINST AN INSURER IS GUILTY OF A CRIME.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2026 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.