

Owner

Rent A Car

Appraiser

review@raestimates.com

Classification

None

Estimate ID

25535664

Original

Claim Number

P

Payer	Loss Type	Claim Number	Policy Number
Customer	Collision		Unit# 685420
Deductible			
None			

2024 Toyota Corolla Hybrid SE 4 Door Sedan 1.8L 4 Cyl Hybrid Injected Auto Trans FWD

Exterior Color	License	VIN	Condition
White	WA-CKZ 1099	JTDBCMFE8RJ020787	Good
Drivable	Odometer	Mitchell Service Code	
No	40223	912163	
Primary Point of Impact	Secondary Point(s) of Impact		
Front (12)	Right Front Corner (1), Right Front Side (2), Left Front Corner (11)		
Unit ID			
685420			

Options				
Air Conditioning	Alum/Alloy Wheels	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)	Auto Air Condition
Automatic Headlights	Auxiliary Input	Bluetooth Wireless Connectivity	Cloth Seat	Cruise Control
Daytime Running Lights	Driver-Front Air Bag	Electric Defogger	Electronic Stability Control	First Row Bucket Seat
HD Radio	Heated Mirror	Keyless Entry System	Leather Steering Wheel	Left-Curtain Air Bag
MP3 Player	Passenger-Front Air Bag	Power Door Locks	Power Remote Mirror	Power Steering
Power Windows	Rear Bench Seat	Rear Spoiler	Rearview Camera	Remote Decklid Or Tailgate Release
Satellite Radio	Second Row Side Airbag With Head Protection	Side Airbags	Smart Key System	Steering Wheel Mounted Audio Control
Telematic Systems	Tilt Steering Wheel	Tire Pressure Monitoring System	Traction Control/Electronic	Trip Computer

2024 Toyota Corolla Hybrid SE

Parts Profile

N/A

Parts Profile Version

N/A

		LABOR				PART				
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Front Bumper										
1	AUTO	Frnt Bumper Cover Assy	Overhaul	Body	3.8#	Existing				
2	202754	Frnt Bumper Cover	Remove / Replace	Body	INC#	New	52119-12999	1		
3	AUTO	Frnt Bumper Cover	Refinish Only	Refinish	2.7 C					
4	202755	R Frnt Bumper Cover Retainer	Remove / Replace	Body	INC#	New	52115-02480	1		
5	AUTO	Frnt Bumper Cover	Remove / Install	Body	INC#					
6	202756	L Frnt Bumper Cover Retainer	Remove / Replace	Body	INC#	New	52116-02460	1		
7	202757	R Frnt Bumper Clip	Remove / Replace	Body	INC	New	90467-05170	1		
8	202758	L Frnt Bumper Clip	Remove / Replace	Body	INC	New	90467-05170	1		
9	202761	R Frnt Bumper Retainer (2 @ \$9.96)	Remove / Replace	Body	INC	New	53879-02150	2		
10	202762	L Frnt Bumper Retainer (2 @ \$9.96)	Remove / Replace	Body	INC	New	53879-02150	2		
11	202763	R Frnt Fender Liner Retainer	Remove / Replace	Body	0.0	New	53879-17020	1		
12	202764	L Frnt Fender Liner Retainer	Remove / Replace	Body	0.0	New	53879-17020	1		
13	202767	R Frnt Bumper Reinforcement Seal	Remove / Replace	Body	INC#	New	16562-F2010	1		
14	202768	L Frnt Bumper Reinforcement Seal	Remove / Replace	Body	INC#	New	16563-F2010	1		
15	202769	R Frnt Bumper Pad	Remove / Replace	Body	INC	New	52421-02050	1		
16	900501	Per Toyota Non-Reusable Part								
17	202770	L Frnt Bumper Pad	Remove / Replace	Body	INC	New	52421-02050	1		
18	900501	Per Toyota Non-Reusable Part								
19	202773	Frnt Bumper Adhesive Emblem	Remove / Replace	Body	0.1#	New	75403-12070	1		
20	900501	Per Toyota Non-Reusable Part								
21	202776	R Frnt Lwr Bumper Cover Extension	Remove / Replace	Body	INC#	New	52112-12260	1		
22	202777	L Frnt Lwr Bumper Cover Extension	Remove / Replace	Body	INC#	New	52113-12220	1		
23	202778	Frnt Bumper Grille	Remove / Replace	Body	INC#	New	53112-12670	1		
24	202828	L Frnt Bumper Cover Grille	Remove / Replace	Body	INC	New	53128-12900	1		
25	202829	L Frnt Bumper Cover Grille	Remove / Replace	Body	INC	New	53128-12903	1		
26	202830	R Frnt Bumper Hole Cover	Remove / Replace	Body	INC	New	81481-12901	1		
27	AUTO	R Frnt Lamp Cover	Refinish Only	Refinish	0.4 C					
28	202831	L Frnt Bumper Hole Cover	Remove / Replace	Body	INC	New	81482-12901	1		

		LABOR				PART				
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
29	AUTO	L Frt Lamp Cover	Refinish Only	Refinish	0.4 C					
30	202832	Frt Bumper License Plate Bracket	Remove / Replace	Body	INC	New	52114-02300	1		
31	202833	Frt Up'r Bumper Impact Absorber	Remove / Replace	Body	INC#	New	52611-12400	1		
32	202834	Frt Lwr Bumper Impact Absorber	Remove / Replace	Body	INC#	New	52618-02310	1		
33	202835	Frt Bumper Reinforcement	Remove / Replace	Body	0.2#	New	52132-02050	1		
34	202838	R Frt Bumper Bracket	Remove / Replace	Body	0.2#	New	52133-02120	1		
35	202839	L Frt Bumper Bracket	Remove / Replace	Body	0.2#	New	52133-02120	1		
36	202842	Frt Bumper Reinforcement Bar	Remove / Replace	Body	0.4#	New	52131-12310	1		
37	202845	R Frt Bumper Reinf Bracket	Remove / Replace	Body	0.2#	New	57013-02100	1		
38	202846	L Frt Bumper Reinf Bracket	Remove / Replace	Body	0.2#	New	57014-12070	1		
Grille										
39	202600	Grille Garnish	Remove / Replace	Body	INC#	New	53141-02180	1		
40	202602	Grille Bracket	Remove / Replace	Body	INC#	New	52149-02060	1		
41	202604	Inr Grille	Remove / Replace	Body	INC#	New	53114-12250	1		
42	202611	Wave Radar Sensor	Remove / Replace	Body	INC#	New	88210-12101	1		
Front Lamps										
43	202609	R Frt Combination Lamp Assembly	Remove / Replace	Body	0.3#	New	81110-12N20	1		
44	AUTO	Headlamps	Check / Adjust	Body	0.4					
45	202610	L Frt Combination Lamp Assembly	Remove / Replace	Body	0.3#	New	81150-12N20	1		
Hood										
46	201836	Hood Panel	Remove / Replace	Body	1.6	New	53301-02480	1		
47	AUTO	Hood Outside	Refinish Only	Refinish	2.5 C					
48	AUTO	Add For Hood Underside	Refinish Only	Refinish	1.3 C					
49	201837	R Hood Hinge	Remove / Replace	Body	0.2#	New	53410-12740	1		
50	AUTO	R Hinge	Refinish Only	Refinish	0.5 C					
51	AUTO	Hood Assy	Remove / Install	Body	INC					
52	201838	L Hood Hinge	Remove / Replace	Body	0.2#	New	53420-12730	1		
53	AUTO	L Hinge	Refinish Only	Refinish	0.5 C					
54	202661	Hood Latch	Remove / Replace	Body	0.3	New	53510-12C02	1		
55	202662	Hood Release Cable	Remove / Replace	Body	1.0	New	53630-12721	1		

		LABOR			PART					
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Cooling										
56	202663	Cooling Radiator -M	Remove / Replace	Mechanical	3.2#	New	16400-F2180	1		
57	AUTO	R Front Combination Lamp	Remove / Install	Body	INC#					
58	AUTO	L Front Combination Lamp	Remove / Install	Body	INC#					
59	AUTO	Bleed Cooling System	Remove / Replace	Body	0.5					
60	201790	Cooling Recovery Tank	Remove / Replace	Body	0.8	New	16470-37040	1		
61	201793	R Cooling Fan Blade	Remove / Replace	Body	0.4#	New	16361-37070	1		
62	AUTO	Radiator -M	Remove / Install	Mechanical	INC#					
63	201794	L Cooling Fan Blade	Remove / Replace	Body	INC#	New	16361-37060	1		
64	202670	Cooling Fan Shroud	Remove / Replace	Body	INC#	New	16711-37150	1		
A/C / Heater / Ventilation										
65	202156	A/C Condenser Assy -M	Remove / Replace	Mechanical	1.0#	New	884A0-0A080	1		
66	AUTO	Evacuate & Recharge A/C - M	Remove / Replace	Mechanical	1.4					
67	202157	Receiver/Drier -M	Remove / Replace	Mechanical	INC#	New	88474-12010	1		
68	900501	Per Toyota Non-Reusable Part								
69	AUTO	A/C Condenser -M	Remove / Install	Mechanical	INC#					
70	202158	A/C Pipe -M	Remove / Replace	Mechanical	1.6	New	88710-12D20	1		
71	202159	Discharge Hose -M	Remove / Replace	Mechanical	0.7	New	88703-16340	1		
Front Fender										
72	200507	R Fender Panel	Remove / Replace	Body	1.8#	New	53801-02170	1		
73	AUTO	R Fender Outside	Refinish Only	Refinish	1.6 C					
74	AUTO	R Add To Edge Fender	Refinish Only	Refinish	0.5 C					
75	200508	L Fender Panel	Remove / Replace	Body	1.8#	New	53802-02260	1		
76	AUTO	L Fender Outside	Refinish Only	Refinish	1.6 C					
77	AUTO	L Add To Edge Fender	Refinish Only	Refinish	0.5 C					
78	202165	L Fender Liner	Remove / Replace	Body	INC#	New	53806-12100	1		
Front Inner Structure										
79	AUTO	Radiator Support Complete	Refinish Only	Refinish	1.5					
80	202565	Frt Body Upper Tie Bar	Remove / Replace	Body	0.5	New	53205-02501	1		
81	AUTO	Upper Tie Bar	Refinish Only	Refinish	INC					

			LABOR			PART			Tax
Line #		Description	Operation	Type	Total Units	Type	Number	Qty	
82	202567	R Frt Body Side Support Assy	Remove / Replace	Body	0.7#	New	53202-47904	1	
83	AUTO	R Side Support	Refinish Only	Refinish	INC				
84	202568	L Frt Body Side Support Assy	Remove / Replace	Body	0.7#	New	53203-47903	1	
85	AUTO	L Side Support	Refinish Only	Refinish	INC				
86	202522	Frt Body Lower Tie Bar	Remove / Replace	Body	0.5	New	53028-02040	1	
87	AUTO	Lower Tie Bar	Refinish Only	Refinish	INC				
88	202508	R Frt Body Air Guide	Remove / Replace	Body	0.2	New	16593-37300	1	
89	202512	L Frt Body Air Guide	Remove / Replace	Body	0.2	New	16595-37280	1	
90	200953	L Frt Body Front Apron Panel -S	Remove / Replace	Body	5.0	New	53702-12A80	1	
91	AUTO	L Apron Assembly Complete	Refinish Only	Refinish	1.5	Existing			
Windshield									
92	201297	W/Shield Washer Reservoir Assy	Remove / Replace	Body	0.5#	New	85315-12730	1	
Front Door									
93	200003	R Frt Door Outside	Blend	Refinish	0.9 C	Existing			
94	200740	L Frt Door Outside	Blend	Refinish	0.9 C	Existing			
95	201503	R Frt Door Trim Panel	Remove / Install	Body	0.5	Existing			
96	201504	L Frt Door Trim Panel	Remove / Install	Body	0.5	Existing			
97	200277	R Frt Otr Door Handle	Remove / Install	Body	0.3#	Existing			
98	200278	L Frt Otr Door Handle	Remove / Install	Body	0.3#	Existing			
Additional Costs & Materials									
99	AUTO	Paint/Materials	Additional Cost						
100	936012	Hazardous Waste Disposal	Additional Cost						
101	936014	Flex Additive	Additional Cost						
102	936003	Coolant	Additional Cost						
Additional Operations									
103	AUTO	Clear Coat	Additional Operation	Refinish	3.4				
104	933049	Calibrate Collision Avoidance System	Additional Operation	Mechanical	0.5*				
105	931127	Pre Repair Scan	Additional Operation	Mechanical	0.5*				
106	931128	Post Repair Scan	Additional Operation	Mechanical	0.5*				
107	933018	Mask For Overspray	Additional Operation	Refinish	0.4*				

* Judgment Item C Included in Clear Coat Calculation

T Included in Two Tone Calculation
Labor Note Applies
d Discontinued by Manufacturer

A Included in Clear Coat and Two Tone Calculation
r CEG R&R Time Used for this Labor Operation
[] Verify the part number and price before ordering

Estimate Totals

Labor	Units	Rate	Sublet	Add'l Amount	Totals
Body Labor	24.8	\$			
Refinish Labor	21.1	\$			
Mechanical Labor	9.4	\$		\$	
Total Labor	55.3				
					Taxable
					Tax 0.0000%
					Non-Taxable
					Pre-Tax Discount 0.00%
					Labor Total
Parts	Amount				
Taxable Parts	\$0.00				
					Parts Adjustments
					Tax 0.0000%
					Non-Taxable
					Pre-Tax Discount 0.00%
					Parts Total
Costs	Amount				
Paint Materials					
Shop Materials					
Other Additional Costs					
Paint Materials:					Taxable
- Refinish Units: 20.7 units					Tax 0.0000%
- Rate: \$50.00					Non-Taxable
- Rate Max: 99.9 units					Pre-Tax Discount 0.00%
- Additional Rate: \$0.00					Costs Total
Gross Totals	Amount				
Gross Total					
					Taxable
					Tax
					Non-Taxable
					Pre-Tax Discount 0.00%
					Gross Total
Adjustments	Amount				
Total Customer Responsibility					
Net Estimate Total					\$1

Estimate Event Log

Job Created11/4/2025 12:00 PM

Estimate Started11/4/2025 12:06 PM

Estimate Printed11/4/2025 12:19 PM

Estimate CommittedEstimate Not Committed

Estimate Retrieval ID1008187103