



EAST COAST COLLISION

3301 SW 14TH PL, STE 2, BOYNTON BEACH, FL 33426
Phone: (561) 734-4164
FAX: (561) 734-3765

Workfile ID: 698f961e
PartsShare: 5xH5G8
Federal ID: 650569452

Preliminary Estimate

Customer: HALEY, KIMBERLY

Job Number:

Written By: RALPH VILONNA

Insured: HALEY, KIMBERLY
Type of Loss:
Point of Impact: 12 Front

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
HALEY, KIMBERLY
(561) 329-8049 Cell

Inspection Location:
EAST COAST COLLISION
3301 SW 14TH PL
STE 2
BOYNTON BEACH, FL 33426
Repair Facility
(561) 734-4164 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2013 INFI G37 Sedan Journey RWD 4D SED 6-3.7L Gasoline Electronic Fuel Injection BLK

VIN: JN1CV6AP7DM713735 Interior Color: Mileage In: 75,661 Vehicle Out:
License: 968QND Exterior Color: BLK Mileage Out:
State: FL Production Date: 9/2012 Condition: Good Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

Rear Side Impact Air Bags

SEATS

Bucket Seats
Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Traction Control
Stability Control
Xenon Headlamps
Power Trunk/Gate Release

Get live updates at www.carwise.com/e/3Ej9zr

Preliminary Estimate

Customer: HALEY, KIMBERLY

Job Number:

2013 INFI G37 Sedan Journey RWD 4D SED 6-3.7L Gasoline Electronic Fuel Injection BLK

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		RESTRAINT SYSTEMS					
2	Repl	Driver air bag sedan black/gray/graphite	Y8E10JK600	1	1,185.64 m	0.3 M	
3		Air bag system diagnosis			m	0.5 M	
4	Repl	Diag unit w/sens sedan	K88203LZ0B	1	1,209.93 m	0.3 M	
5	Repl	LT Belt & retractor w/o Technology package black/graphite	86885JK60B	1	319.04	0.6	
6	Repl	Ft impact sensor coupe, sedan	K85811GZ0A	1	419.82 m	0.4 M	
7	Repl	LT Buckle end black/graphite	86843JK60B	1	66.89	0.2	
8		RADIATOR SUPPORT					
9	* Repl	<u>LKQ Front sheet metal +25%</u>	62501JK05A	1	<u>3,437.50</u>	<u>6.9</u>	<u>8.8</u>
10		Evacuate & recharge			m	1.4 M	
11		Refrigerant recovery			m	0.4 M	
12		FRONT BUMPER					
13		O/H bumper assy				2.1	
SUBTOTALS					6,638.82	13.1	8.8

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			6,638.82
Body Labor	9.8 hrs @	\$ 48.00 /hr	470.40
Paint Labor	8.8 hrs @	\$ 48.00 /hr	422.40
Mechanical Labor	3.3 hrs @	\$ 100.00 /hr	330.00
Paint Supplies	8.8 hrs @	\$ 30.00 /hr	264.00
Subtotal			8,125.62
Sales Tax	Tier 1	\$ 5,000.00 @ 7.0000 %	350.00
Sales Tax	Tier 2	\$ 3,125.62 @ 6.0000 %	187.54
Grand Total			8,663.16

THIS IS ONLY A ESTIMATE THERE MAY BE HIDDEN DAMAGE THAT AT THIS TIME CAN NOT BE SEEN.THAT WOULD BE SUPPLEMENTAL.THIS ESTIMATE IS ONLY GOOD FOR 90 DAYS.WE ARE NOT RESPONSIBLE FOR ANY PRICE DIFFERENCES.THIS CHARGE REPRESENTS COSTS AND TO THE MOTOR VECHICLE REPAIR FACILTY FOR MISCELLANEOUS SHOP SUPPLIES OR WASTE DISPOSAL. [s . 559 .904 (40) } ALL REPAIRS GUARANTEED FOR 90 DAYS OF REPAIRS.UNLESS SPECIFIED BY INS. CO.