

## VEHICLE

2021 NISS Altima SV 4D SED 4-2.5L Gasoline Gasoline Direct Injection GREY

VIN: 1N4BL4DV6NN300915

Production Date:

Interior Color:

License: DCC6218

Odometer: 984

Exterior Color: GREY

State: FL

Condition:

### TRANSMISSION

Automatic Transmission

### POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat

### DECOR

Dual Mirrors

Tinted Glass

Console/Storage

Overhead Console

### CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Remote Starter

Backup Camera

Parking Sensors

### RADIO

AM Radio

FM Radio

Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio

### SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

Rear Side Impact Air Bags

Blind Spot Detection

Lane Departure Warning

### SEATS

Cloth Seats

Bucket Seats

### WHEELS

Aluminum/Alloy Wheels

### PAINT

Clear Coat Paint

### OTHER


Traction Control

Stability Control

Xenon or L.E.D. Headlamps

Power Trunk/Liftgate

Line	Oper	Description	Part Number	Qty	E
1	#	1N4BL4DV6NN300915 THIS IS A 2022 MODEL WITH NO DATA BASE		1	
2	#	USING THE 2021 MODEL DATA BASE FOR THIS ESTIMATE		1	
3	<b>HOOD</b>				
4	Blnd	Hood			
5	<b>FENDER</b>				
6	Repl	LT Fender	631016CA0A	1	
7		Add for Edging			
8		Add for Clear Coat			
9	Repl	LT Baffle plate	631316CA0A	1	
10	Repl	LT Fender liner w/alloy wheels	638416CA0A	1	
11	<b>WHEELS</b>				
12	*	Repl LT/Front Wheel, alloy 17"	403006CA4A	1	
13	#	MOUNT AND BALANCE		1	
14	#	ALIGNMENT		1	
15	<b>RESTRAINT SYSTEMS</b>				
16	Repl	Diag unit w/sens	988209HE9A	1	
17	Repl	LT Head air bag	985P19HB8A	1	
		Note: LABOR: Time is after headliner is removed.			
		WARNING:			
		Prior to repairing any restraint system components or wiring, the battery cable(s) must be disconnected and any back-up power supply must be discharged in order to prevent accidental deployment. Certain safety precautions must also be followed when servicing or handling supplemental restraint system components. Refer to the applicable MOTOR Air Bag Manual, Air Bag Quick Reference Guide or Air Bag Diagnostic CD for supplemental restraint system disarming procedures and Safety and Service Precautions.			
		NOTE:			
		Restraint System information is for estimating purposes only.			
		Labor times for airbag diagnosis are based on OEM procedures.			
		REPLACEMENT COMPONENTS			
		This is the latest information available at the time of compilation and supersedes all prior information published by MOTOR. Check with the OEM or authorized dealer to obtain the most current information available.			
		FRONT DEPLOYMENT			
		Deployed air bag module(s)			
		Air bag module fastener(s)			
		Diagnostic unit			
		Diagnostic unit			



fastener(s)  
 Clockspring  
 Pre-tensioner(s)  
 Pre-tensioner  
 fastener(s)  
 Instrument panel,  
 (integrated type),  
 if passenger air bag  
 deployed  
 Front impact sensor  
 and bracket  
 Front impact sensor  
 fastener(s)  
 SIDE DEPLOYMENT  
 Deployed air bag  
 module(s)  
 Air bag module  
 fastener(s)  
 Diagnostic unit  
 Diagnostic unit  
 fastener(s)  
 Side impact sensor, in  
 area of impact  
 Side impact sensor  
 fastener(s)  
 Pre-tensioner(s)  
 Pre-tensioner  
 fastener(s)  
 Seat back assembly, on  
 side of impact  
 if air bag deployed  
 INSPECTION COMPONENTS  
 Undeployed air bag  
 module(s)  
 Steering wheel  
 Harness  
 Connectors  
 Headliner  
 Interior trim  
 Center pillar inner  
 ADD IF REQUIRED  
 Air bag  
 system diagnosis                      19-21                      m 0.5

18	Repl	LT Side impact sens front door	988365NA6B	1
19	Repl	LT Side impact sens center pillar	988305NA6A	1
20	Repl	RT Belt & retractor charcoal	868846CA8A	1
21	Repl	LT Belt & retractor charcoal	868856CA8A	1
22	Repl	RT Buckle charcoal	868426CA9A	1
23	Repl	LT Buckle charcoal	868426CA8A	1
24	<b>SEATS &amp; TRACKS</b>			
25	Repl	Seat back assy w/o leather, SV charcoal	876006CA1A	1
26	Repl	LT Seat back assy w/o leather, FWD charcoal	886556CA0A	1

27	<b>ROOF</b>				
28		Repl	Headliner 2.5L	739116CJ0A	1
29	<b>PILLARS, ROCKER &amp; FLOOR</b>				
30		Sect	LT Aperture panel (HSS) cut below roof line	G60336CAMA	1
31			Overlap Major Adj. Panel		
32	<b>FRONT DOOR</b>				
33		Repl	LT Applique SL, SV, Platinum	808136CA1A	1
34		Repl	LT Door shell	801016CA0A	1
35			Overlap Major Adj. Panel		
36		Repl	LT Mirror cover	963746CA9A	1
37			Overlap Minor Panel		
38		Repl	LT Mirror outside SL, SV	963026CA1B	1
39		Repl	LT Lower hinge	804006CA0A	1
40		Repl	LT Upper hinge	804016CA0A	1
41	<b>REAR DOOR</b>				
42	*	Rpr	LT Door shell (HSS)		
43			Overlap Major Adj. Panel		
44			Clear Coat		
45		R&I	LT Belt molding		
46		R&I	LT Handle, outside chrome		
47		R&I	LT R&I trim panel		
48	<b>VEHICLE DIAGNOSTICS</b>				
49	*	Subl	Pre-repair scan		1
50	*	Subl	Post-repair scan		1
51	#		SET UP & MEASURE		1
52	#		PULL TIME		1
53	#		REPAIR UNIBODY CLAMP DAMAGE		1
54	#	Refn	COLOR MATCH		
55	#		SEAM SEALER		1
56	#		CORROSION PROTECTION		1
57	#		COVER CAR		1
58	#		HAZ WASTE		1

Note: PARTS: Part has related component that cannot be reused/reinstalled; applique.

