









Inspection

Inspection Date: 09/09/2025 05:48 PM

Inspection Type:



Target Complete Date/Time:

Days To Repair: 16

Vehicle

2024 Nissan Sentra S 4 DR Sedan
4cyl Gasoline 2.0 Dohc
6 Speed Manual

Lic Expire:
Veh Insp# :
Condition:
Ext. Colour: black
Ext. Refinish: Two-Stage

VIN: 3N1AB8BV9RY248338
Kilometer Type: Actual
Code: Z1795A
Int. Colour:
Int. Refinish:

Options

1st Row LCD Monitor(s)	2nd Row Head Airbags	AM/FM Radio
Active Blind Zone Assist	Adjustable Seat System	Air Conditioning
Aluminum/Alloy Wheels	Anti-Lock Brakes	Armrest(s)
Auto Emergency Braking	Automatic High Beam	Auxiliary Audio Input
Black Exterior Trim	Black Grille	Blind Spot Sensor
Cargo Lamp	Carpeting	Color-Keyed Bumper(s)
Cruise Control	Daytime Running Lights	Digital Clock
Driver Attention Monitor	Driver Information Sys	Driver Knee Airbag
Dual Airbags	Elect. Stability Control	Engine Stop/Start

Fwd. Collision Alert	Halogen Headlights	Head Airbags
Heated Front Seats	Heated Power Mirrors	Inside Rearview Mirror
Interior Lighting	Intermittent Wipers	Keyless Entry System
Lane Departure Alert	Lighted Entry System	Limited Slp Differential
Overhead Console	Passenger Knee Airbag	Power Door Locks
Power Rear Window	Power Windows	Pwr Accessory Outlet(s)
Rear Collisn Mitigation	Rear Side Airbags	Rear View Camera
Rear Window Defroster	Reverse Sensing System	Seat(s) Height Adjustmnt
Side Airbags	Strg Wheel Radio Control	Telescopic Steering Whl
Temperature Gauge(s)	Theft Deterrent System	Tinted Glass
Tire Pressure Monitor	Touch Screen Display	Trip Computer
USB Audio Input(s)	Velour/Cloth Seats	Wireless Audio Streaming
Wireless Phone Connect		

Damages										
Line	Op	Guide	MC	Description	MFR.Part No.		ADJ%	B%	Hours	R
Front End Panel And Lamps										
1	E	41		Headlamp Assy, Halogen LT	260606LY0A				1.3	SM
2	N	973		Headlamps Aim	Additional Labour				0.4	SM
Front Body And Windshield										
3	E	83	01	Panel, Hood	FE1006LBMA				1.1	SM
4	L	83	13	Panel, Hood	Refinish				5.4	RF
5	SB	103		Fender, Front LT	Sublet Repair					SM
				>> PDR-Moderate - 16 To 30, Quarter						
6	SB	104		Fender, Front RT	Sublet Repair					SM
				>> PDR-Very Light - 1 To 5, Nickel						
7	NG	143		W/S, Tinted Adas (s)	NAGS FW5207-GT				2.2	SM
Roof										
8	E	341		Panel, Roof	G31126LYMA				11.2	SM
9	L	341		Panel, Roof	Refinish				3.8	RF
Dashboard And Components										
10	N	1248		Scan, Pre-Repair	Additional Labour				0.3	ME
11	N	1249		Scan, Post-Repair	Additional Labour				0.3	ME
12	N	1350		Clbrt, Int Camera (s)	Additional Labour				0.6	ME
Front Doors										
13	SB	207		Door Shell, Front LT	Sublet Repair					SM
				>> PDR-Medium - 31 To 50, Nickel						
14	SB	208		Door Shell, Front RT	Sublet Repair					SM
				>> PDR-Very Light - 1 To 5, Quarter 1 o/s						
15	E	271		Mldg, Front Door Belt LT	808216LA5A				0.3	SM
16	E	272		Mldg, Front Door Belt RT	808206LA5A				0.3	SM
Rear Doors										
17	SB	287		Door Shell, Rear LT	Sublet Repair					SM
				>> PDR-Medium - 31 To 50, Quarter						
18	SB	288		Door Shell, Rear RT	Sublet Repair					SM
				>> PDR-Very Light - 1 To 5, Dime						
19	E	334		Mldg, Rear Door Belt LT	828216LA5A				0.2	SM
20	E	335		Mldg, Rear Door Belt RT	828206LA5A				0.2	SM
Quarter And Rocker Panel										
21	I	173	07	Panel, Bodyside Otr UpR LT	Repair				12.0*	SM
22	L	173		Panel, Bodyside Otr UpR LT	Refinish				2.8	RF

23	SB	174	Panel,Bodyside Otr Upr RT >> PDR-Medium - 31 To 50, Nickel	Sublet Repair	SM
24	SB	389	Panel,Quarter LT >> PDR-Moderate - 16 To 30, Quarter	Sublet Repair	SM
25	SB	390	Panel,Quarter RT >> PDR-Light - 6 To 15, Nickel	Sublet Repair	SM

Deck Lid And Back Glass

26	NG	369		Back Glass,Heated	NAGS FB28229-GT	2.2	SM
27	L	479		Deck Lid Assembly	Refinish	3.8	RF
28	E	479	01	Lid,Rear Deck Adas (s)	HD3006LTBB	2.8	SM
29	E	496		N/Plate,Deck Lid	848906LB0A	0.2	SM
30	E	535	01	Emblem,Deck Lid	848966LY0B	0.2	SM
30 Items							


MC	Message
01	CALL DEALER FOR EXACT PART # / PRICE
07	STRUCTURAL PART AS IDENTIFIED BY I-CAR
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

ClaimID: FF31666C-09C6-43F1-B636-0B1616B639A1
Rate Name Default

Op Codes


* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labour	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labour
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	





Year: 2024
Make: Nissan
Model: Sentra
Color: Black

Vin: 3N1AB8BV9RY248338
Stock/Ro#: 16462051
Odometer:
License:



Service Type	Description	Body Hours	Paint Hours
LT Fender PDR - \$400.00 PDR	16-30 dents, Quarter	--	--
RT Fender PDR - \$145.00 PDR	1-5 dents, Nickel	--	--
LT Front Door PDR - \$370.00 PDR	31-50 dents, Nickel	--	--
RT Front Door PDR - \$215.00 PDR Add-On	1-5 dents, Quarter Oversized Dents, 1 @ \$50.00	-- --	-- --
LT Rear Door PDR - \$470.00 PDR	31-50 dents, Quarter	--	--
RT Rear Door PDR - \$90.00 PDR	1-5 dents, Dime	--	--
RT Roof Rail PDR - \$475.00 PDR	31-50 dents, Nickel	--	--
LT Quarter PDR - \$525.00 PDR	16-30 dents, Quarter	--	--
RT Quarter PDR - \$275.00 PDR	6-15 dents, Nickel	--	--

