



CONDITION REPORT

Stock: 204600
Unit:
Customer:
Lot:

AutoNation
AUTO AUCTION

Date: 07/31/2025 09:24 AM
Seller: AUTONATION TOYOTA
SOUTH AUSTIN #AN2571
Phone/Fax: (512) 440-4500/(512)
440-5006
Sale Date:

Year 2022	Make TOYOTA		Model COROLLA SE		Body Type 4dr Car	VIN JTDS4MCE1N3509726
Drive FWD	Ext Color White	Int Color Black	Int Material Cloth		Sound AM/FM	Roof Hard Top
Fuel Gas	Mileage 24985	Odo. Type Digital	Engine 4-Cyl. 2.0Liters		Transmission Automatic	Airbags
Doors 4	License Plate		License St	Plates	Plate Expires	End of Term

- Accessories:** Stereo, (AM/FM Radio) Keyless entry (Left)
- Interior:** Ok odor, Pass-through rear seat, Leather steering wheel, Radio-satellite, Side airbags - front, Steering wheel controls, Power mirrors, Seat trim, (Cloth) Pass. air bag, Led headlights, Security alarm, Mp3 player, Power windows, Intelligent cruise control, Side airbags - rear, Power locks, Keyless start, Bluetooth connection, Heated mirrors, Driver air bag, Tilt steering wheel, Traction control, Rear defroster, Cruise control
- Exterior:** Wheels rear right, (Aluminum) Rear spoiler, Wheels front right, (Aluminum) Spare tire, (Space Saver) Child safety locks, Wheels rear left, (Aluminum) Wheels front left, (Aluminum) Turn signal mirrors
- Equipment:** Engine immobilizer, Automatic headlights, Lane departure system, Power steering, Brake assist system, Independent climate control, Front wheel drive, Combo key, (1) Intermittent wipers, Remote trunk release, Power brakes, Antilock brake system, Daytime running lights, Air conditioner
- Electronics:** Tire pressure monitor system, Collision avoidance, Telematics, Reverse camera, Trip computer
- Other:** Cylinders (4) , Motor fuel type (Gas) , Transmission (Automatic Transmission)

Notification:

Arrival: 05/27/2025

Visual: 07/31/2025

Body: 07/31/2025

Mechanical:

Writer: Rafael Esp

Approval:

Complete: 07/31/2025

Revised:

Driveable: Yes

Visual Frame _Y

Damage:

Book Value: \$18025.00

Tires	Left	Right
Front	07/32in Other P225/40VR18	07/32in Other P225/40VR18
Rear	07/32in Other P225/40VR18	07/32in Other P225/40VR18
Spare		



AutoGrade
Grade 1.8 Rough
[About AutoGrade](#)

Announcements:

- Structural damage

Notes:

Inspection Date	Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
Chargeable									
07/31/2025	Battery inoperable			150.00	0.00	0.00	0.00	0.00	0.0

	- Repair Required.						
07/31/2025	Front bumper cover misaligned	0.00	1.00	0.00	0.00	0.00	0.0
	- Repair Required.						
07/31/2025	Front bumper cover scratch heavy	0.00	0.00	0.00	1.00	0.00	0.0
	- 1/2 To 1 Inch.						
07/31/2025	R b pillar kinked	0.00	0.00	0.00	0.00	0.00	0.0
	- 5 to 6in.						
07/31/2025	Right drip rail mult dents/paint dam	200.00	0.00	0.00	0.00	0.00	0.0
	- 10 or more.						
07/31/2025	Rf door glass broken	60.00	0.00	0.00	0.00	0.00	0.0
	- Replacement Required.						
07/31/2025	Rf door severe damage	500.00	0.00	0.00	0.00	0.00	0.0
	- Replacement Required.						
07/31/2025	Rf fender mult dents/paint dam	0.00	0.00	0.00	0.00	0.00	0.0
	- 10 or more.						
07/31/2025	Rf mirror housing broken	70.00	0.00	0.00	0.00	0.00	0.0
	- Replacement Required.						
07/31/2025	Rf window broken	120.00	0.00	0.00	0.00	0.00	0.0
	- Replacement Required.						
07/31/2025	Rr door severe damage	500.00	0.00	0.00	0.00	0.00	0.0
	- Replacement Required.						
Subtotal:		\$1600.00	1.00	\$0.00	1.00	\$0.00	\$0.00
Deductible							
Subtotal:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Nonchargeable							
Subtotal:		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Total Estimate:		\$1600.00	1.00	\$0.00	1.00	\$0.00	\$0.00
Grand Total:						\$1600.00	

Charge Date	Description	Amount
Total Charges:		\$0.00



Photo left rear



Photo rear



Photo right rear



Photo right front



Photo interior



Photo dash



Photo engine



Photo odometer




Photo wheel



Photo deck



Photo vin/id sticker



Steering wheel



Stereo



Left rear seat



Roof



Keys



Door panels



Deck lid badge



Front bumper cover
scratch heavy



Front bumper cover
misaligned




Rr door severe damage



Right drip rail mult
dents/paint dam



Rf fender mult
dents/paint dam



Rf door glass broken




Rf door severe damage



R b pillar kinked



Rf window broken



Rf mirror housing
broken



Battery inoperable

AUTO NATION AA -
HOUSTON

608 W MITCHELL RD, HOUSTON, 77037

(281) 506-3220

204600