



CONDITION REPORT

Stock: 204599
Unit:
Customer:
Lot:

AutoNation
AUTO AUCTION

Date: 07/31/2025 09:26 AM
Seller: AUTONATION TOYOTA
SOUTH AUSTIN #AN2571
Phone/Fax: (512) 440-4500/(512)
440-5006
Sale Date:

Year 2024	Make TOYOTA	Model COROLLA CROSS HYBR	Body Type Sport Utility	VIN 7MUFBABG8RV038600
Drive AWD	Ext Color Black	Int Color Black	Int Material Cloth	Sound AM/FM
Fuel Hybrid Gasoline	Mileage 15733	Odo. Type Digital	Engine 4-Cyl. 2.0Liters	Transmission Automatic
Doors 4	License Plate	License St	Plates	Plate Expires
				End of Term

- Accessories:** Stereo, (AM/FM Radio) Keyless entry remote(s), (1) Keyless entry (Left)
- Interior:** Ok odor, Pass-through rear seat, Radio-satellite, Side airbags - front, Steering wheel controls, Power mirrors, Seat trim, (Cloth) Pass. air bag, Led headlights, Mp3 player, Power windows, Intelligent cruise control, Side airbags - rear, Power locks, Keyless start, Bluetooth connection, Heated mirrors, Driver air bag, Tilt steering wheel, Traction control, Hd radio, Rear defroster, Cruise control
- Exterior:** Wheels rear right, (Aluminum) Rear spoiler, Wheels front right, (Aluminum) Child safety locks, Wheels rear left, (Aluminum) Wheels front left (Aluminum)
- Equipment:** Engine immobilizer, Automatic headlights, All wheel drive, Lane departure system, Power steering, Brake assist system, Independent climate control, Intermittent wipers, Remote trunk release, Power brakes, Antilock brake system, Daytime running lights, Air conditioner
- Electronics:** Tire pressure monitor system, Collision avoidance, Telematics, Reverse camera, Trip computer
- Other:** Cylinders (4) , Motor fuel type (Other) , Transmission (Automatic Transmission)

Notification:

Arrival: 05/27/2025

Visual: 07/31/2025

Body: 07/31/2025

Mechanical:

Writer: Rafael Esp

Approval:

Complete: 07/31/2025

Revised:

Driveable: Yes

Visual Frame Y

Damage:

Book Value: \$26925.00

Tires	Left	Right
Front	07/32in Other P215/65HR17	07/32in Other P215/65HR17
Rear	07/32in Other P215/65HR17	07/32in Other P215/65HR17
Spare		



AutoGrade
Grade 1.6 Rough
[About AutoGrade](#)

Announcements:

- Structure damage

Notes:

Inspection Date	Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
Chargeable									
07/31/2025	Front bumper scuffed			0.00	0.00	0.00	0.00	0.00	0.0

	- 11 to 12in.						
07/31/2025	Hood scuffed - GR 12in.	0.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	L qtr panel dents w/no paint dmg - PDR/1.	0.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	R qtr panel severe damage - Replacement Required.	700.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	R d pillar kinked - 6 to 7in.	0.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Right drip rail mult dents/no paint - 5.	0.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Right drip rail scratch heavy - GR 12in.	0.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Rf door severe damage - Replacement Required.	700.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Rf fender severe damage - Replacement Required.	100.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Rf mirror severe damage - Replacement Required.	200.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Rr door severe damage - Replacement Required.	800.00	0.00	0.00	0.00	0.00	0.0
07/31/2025	Rr tail lamp broken - Replacement Required.	100.00	0.00	0.00	0.00	0.00	0.0
<i>Subtotal:</i>		\$2600.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<i>Deductible</i>							
<i>Subtotal:</i>		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<i>Nonchargeable</i>							
<i>Subtotal:</i>		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Total Estimate:		\$2600.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Grand Total:						\$2600.00	

Charge Date	Description	Amount
Total Charges:		\$0.00



Photo left rear



Photo rear



Photo right rear



Photo right front




Photo interior



Photo dash



Photo engine



Photo odometer



Photo wheel

Photo deck

Photo vin/id sticker

Stereo



Left rear seat



Roof



Keys



Door panels



Deck lid badge



Front bumper scuffed




Hood scuffed







L qtr panel dents w/no
paint dmg




R d pillar kinked



Rr door severe damage



Rr tail lamp broken




Right drip rail mult
dents/no paint



Right drip rail scratch
heavy



R qtr panel severe
damage



Rf door severe damage



Rf fender severe damage



Rf mirror severe damage

AUTO NATION AA -
HOUSTON

608 W MITCHELL RD, HOUSTON, 77037

(281) 506-3220

204599