

*** PRELIMINARY ESTIMATE ***

01/29/2026 11:36 AM

Owner

[REDACTED]
FAX:

Control Information

Claim # [REDACTED]

Insured Policy # :

Inspection



Repairer



Target Complete Date/Time:

Days To Repair: 8

Vehicle

2026 Hyundai Tucson SEL 4 DR Wagon

4cyl Gasoline 2.5

8-Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 5NMJBCDE5TH608591
Mileage Type: Actual
Code: E7234A
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)
AM/FM Radio
Aluminum/Alloy Wheels
Assisted Driving Vehicle
Automatic High Beam
Blind Spot Sensor

2nd Row Head Airbags
Adjustable Seat System
Anti-Lock Brakes
Auto Emergency Braking
Automatic Power Locks
Bucket Seats

4-Wheel Drive
Alarm System
Armrest(s)
Auto Headlamp Control
Black Grille
Carpeting

| | | |
|--------------------------|--------------------------|--------------------------|
| Center Console | Collision Avoidance Sys | Color-Keyed Bumper(s) |
| Compact Spare Tire | Corrective Lane Assist | Cross Traffic Alert |
| Cruise Control | Digital Clock | Digital Instrument Panel |
| Driver Attention Monitor | Driver Information Sys | Dual Airbags |
| Dual Zone Auto A/C | Elect. Stability Control | Electric Parking Brake |
| Electronic Transfer Case | Emergency S.O.S. System | Engine Stop/Start |
| Fwd. Collision Alert | Hands Free Liftgate | Head Airbags |
| Heated Front Seats | Heated Power Mirrors | Heated Windshield |
| In-Vehicle WiFi | Inside Rearview Mirror | Intelligent Cruise Cntrl |
| Intermittent Wipers | Keyless Entry System | Keyless Ignition System |
| LED Daytime Running Lts | LED Headlamps | Lane Departure Alert |
| Navigation System | Overhead Console | Pedestrian Detection Sys |
| Perimeter Alarm System | Power Door Locks | Power Drivers Seat |
| Power F & R Disc Brakes | Power Liftgate/Tailgate | Power Windows |
| Pwr Accessory Outlet(s) | Pwr Driver Lumbar Supp | Rear Collisn Mitigation |
| Rear Lip Spoiler | Rear Side Airbags | Rear View Camera |
| Rear Window Defroster | Rear Window Wiper/Washer | Remote Starter |
| Roof Rails | Seat(s) Height Adjustmnt | Security Alarm System |
| Side Airbags | Single Exhaust System | SiriusXM Satellite Radio |
| Split Folding Rear Seat | Spring Suspension | Stability Cntrl Suspensn |
| Stop & Go System | Strg Wheel Radio Control | Temperature Gauge(s) |
| Theft Deterrent System | Tilt & Telescopic Steer | Tinted Glass |
| Tire Pressure Monitor | Touch Screen Display | Trip Computer |
| U.S.A. Built Vehicle | USB Audio Input(s) | Vehicle Tracking Service |
| Velour/Cloth Seats | Wireless Audio Streaming | Wireless Phone Connect |

Damages

| Line | Op | Guide | MC | Description | MFR.Part No. | Price | ADJ% | B% | Hours | R |
|----------------------------------|----|-------|----|--------------------------|---|-------|------|----|-------|--------|
| Stripes And Mouldings | | | | | | | | | | |
| 1 | E | 141 | | Mldg,Wheel Opening LT | 877W5CW500CA | | | | | INC SM |
| 2 | RI | 267 | | Mldg,Front Door Lower LT | R & I Assembly | | | | | 0.2 SM |
| Front Bumper | | | | | | | | | | |
| 3 | E | 6 | | Cover,Front Bumper | 86511CW500 | | | | | 4.4 SM |
| 4 | L | 6 | 13 | Cover,Front Bumper | Refinish 2.0 Surface 0.6 Two-stage setup 0.4 Two-stage | | | | | 3.0 RF |
| 5 | E | 26 | | Mldg,Frt Bumper Cover | 86599CW500 | | | | | 0.1 SM |
| 6 | E | 99 | | Mldg,Frt Bumper Cover | 86577CW500PXP | | | | | 0.2 SM |
| 7 | E | 2035 | | Mldg,Frt Bumper Cover LT | 86595CW520 | | | | | INC SM |
| 8 | E | 93 | | Grille,Frt Bumper Lwr | 86531CW500CA | | | | | 0.2 SM |
| 9 | E | 1013 | | Spoiler,Lower Front | 86591CW500CA | | | | | INC SM |
| 10 | E | 1442 | | Duct,Air Intake LT | 86543CW500 | | | | | INC SM |
| 11 | E | 1448 | | Filler,Front Bumper LT | 865C1CW500CA | | | | | INC SM |
| 12 | RI | 20 | | Panel,Frt Bmpr License | R & I Assembly | | | | | 0.1 SM |
| 13 | E | 43 | | Brkt,Front Bumper Mtg LT | 86551CW500 | | | | | INC SM |
| 14 | E | 111 | | Brkt,Front Bumper Mtg LT | 865E1CW500 | | | | | INC SM |
| Front End Panel And Lamps | | | | | | | | | | |
| 15 | E | 27 | | Grille Assembly | 86350N9GA0TTY | | | | | INC SM |
| 16 | E | 41 | | Headlamp Assy,Led LT | 92101CW650 | | | | | 0.2 SM |
| 17 | N | 973 | | Headlamps Aim | Additional Labor | | | | | 0.4 SM |
| 18 | E | 94 | | Lamp Assembly,Running LT | 92207CW510 | | | | | INC SM |
| Front Body And Windshield | | | | | | | | | | |
| 19 | E | 103 | | Fender,Front LT | 66311CW010 | | | | | 1.3 SM |

| | | | | | | |
|---------------------------------------|----|------|--------------------------|--|------|--------|
| 20 | L | 103 | Fender,Front LT | Refinish 2.3 Surface 0.5 Edge 0.6 Two-stage | 3.4 | RF |
| 21 | E | 1092 | Seal,Front Fender LT | 84116CW000 | | INC SM |
| Front Body Interior Sheetmetal | | | | | | |
| 22 | E | 119 | Skirt,Inner Fender LT | 86811CW500 | | INC SM |
| Front Doors | | | | | | |
| 23 | I | 207 | Door Shell,Front LT | Repair | 4.0* | SM |
| 24 | L | 207 | Door Shell,Front LT | Refinish 2.3 Surface 0.5 Two-stage | 2.8 | RF |
| 25 | RI | 1567 | W/Strip,Belt Outer LT | R & I Assembly | 0.1 | SM |
| 26 | RI | 231 | Pnl,Inner Door Trim LT | R & I Assembly | INC | SM |
| 27 | RI | 229 | Mirror,Outer R/C LT | R & I Assembly | 0.7 | SM |
| 28 | RI | 334 | Handle,Front Door Otr LT | R & I Assembly | 0.2 | SM |
| Manual Entries | | | | | | |
| 29 | L | M14 | Corrosion Protection | Refinish | 0.3* | RF |
| 30 | L | M15 | Color Tint | Refinish | 0.8* | RF* |
| 31 | L | M17 | Cover Car Exterior | Refinish | 0.2* | RF |
| 32 | N | | Pre-scan | Additional Labor | 1.0* | ME* |
| 33 | N | | Post-scan | Additional Labor | 1.0* | ME* |
| 33 Items | | | | | | |

MC **Message**

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts
Other Parts
Paint & Materials
Parts & Material Total

10.5 Hours @ [REDACTED]

| Labor | Rate | Replace Hrs | Repair Hrs | Total Hrs |
|-------|------|-------------|------------|-----------|
|-------|------|-------------|------------|-----------|

| | | | | |
|------------------|------------|------|-----|------|
| Sheet Metal (SM) | [REDACTED] | 7.7 | 4.4 | 12.1 |
| Mech/Elec (ME) | [REDACTED] | | 2.0 | 2.0 |
| Frame (FR) | [REDACTED] | | | |
| Refinish (RF) | [REDACTED] | 10.5 | | 10.5 |

Labor Total 24.6 Hours

Gross Total

Net Total

ClaimID: 114A3191-E58E-4648-BA03-2ED98035BFCA

Alternate Parts No

SPPL Yes Zip Code: 00000 Default

Rate Name Default

10.34.134 ES 01/29/2026 11:46 AM REL 10.34.134 DT 01/01/2026 DB 01/22/2026

State Disclosure:MN

2.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE. A PERSON WHO FILES A CLAIM WITH INTENT TO DEFRAUD OR HELPS COMMIT A FRAUD AGAINST AN INSURER IS GUILTY OF A CRIME.

Op Codes

* = User-Entered Value
NG = Replace NAGS
UE = Replace OE Surplus
EU = Replace Recycled
UM = Replace Reman/Rebuilt
UC = Replace Reconditioned
N = Additional Labor
IT = Partial Repair
P = Check

^ = Labor Matches System Assigned Rates
EC = Replace Economy
ET = Partial Replace Labor
TE = Partial Replace Price
L = Refinish
TT = Two-Tone
BR = Blend Refinish
CG = Chipguard
AA = Appearance Allowance

E = Replace OEM
OE = Replace PNX OE Srpls
EP = Replace PNX
PM = Replace PNX Reman/Reblt
PC = Replace PNX Reconditioned
SB = Sublet Repair
I = Repair
RI = R & I Assembly
RP = Related Prior Damage

This report contains proprietary information of [REDACTED] and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without [REDACTED] prior written consent.